

WESTINGHOUSE ELECTRIC CORP, MICARTA DIV -- MICARTA GRADES -- 5970-01-109-4927
===== Product Identification =====

Product ID:MICARTA GRADES

MSDS Date:05/01/1996

FSC:5970

NIIN:01-109-4927

MSDS Number: CDXLJ

=== Responsible Party ===

Company Name:WESTINGHOUSE ELECTRIC CORP, MICARTA DIV

Address:304 HOOVER ST

Box:248

City:HAMPTON

State:SC

ZIP:29924-1105

Country:US

Info Phone Num:803-943-2311

Emergency

Phone Num:803-943-7200

CAGE:76435

=== Contractor Identification ===

Company Name:INTERNATIONAL PAPER DECORATIVE PRODUCTS DIVISION

Address:304 HOOVER ST

Box:City:HAMPTON

State:SC

ZIP:29924-1105

Country:US

Phone:803-943-7200

CAGE:76435

===== Composition/Information on Ingredients =====

Ingred Name:ALPHA-ALUMINA (ALUMINUM OXIDE) (SARA 313)

CAS:1344-28-1

RTECS #:BD1200000

Fraction by Wt: 0-33%

Other REC Limits:NONE RECOMMENDED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 95

Ingred Name:DUST, NUISANCE
Other REC Limits:NONE RECOMMENDED

Ingred Name:FIBROUS GLASS DUST
Other REC Limits:NONE RECOMMENDED

Ingred Name:GLASS CLOTH/FABRIC
Other REC Limits:NONE RECOMMENDED

Ingred Name:EPOXY COMPOSITE
Other REC Limits:NONE RECOMMENDED

=====
===== Hazards Identification =====

LD50 LC50 Mixture:NONE SPECIFIED BY MANUFACTURER.

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Haz

ards Acute and Chronic:EXPO FROM ROUTINE USE:DUST CAN CAUSE
IRRIT TO EYES/NOSE/THROAT/LUNGS/SKIN.

Explanation of Carcinogenicity:PER MSDS:GLASS CLOTH OR FILAMENT-EPOXY
COMPOSITE HAS NOT BEEN EVALUATED FOR CARCINOGENICITY.

Effects of Overexposure:PROLONGED EXPOSURE TO DUST MAY CAUSE IRRIT IN
EYES,NOSE,THROAT/OR MOUTH.

Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

=====
===== First Aid Measures =====

First Aid:EYE:FOR DUST RINSE I

MMED W/WATER.REMOVE CONTACT LENSES,THEN

FLUSH W/LG QUANTITIES OF WATER FOR @LEAST 15MINS.SEEK MED

ATTN.SKIN:ROUTINE SKIN CONTACT W/COMPOSITE OR COMPOSITE DUST IS

UNLIKELY TO CAUSE ANY HAZARD.INHAL:FOR DUST REMOVE TO FRESH

AIR.SEEK MED ATTN IF NECESSARY.INGEST:INGESTION OF COMPOSITE OR

COMPOSITE DUST IS UNLIKELY TO OCCUR IN INDUSTRIAL OR COMMERCIAL
USE.

=====
===== Fire Fighting Measures =====

Flash Point Method:PMCC

Flash Point:NONE

Autoigni

tion Temp:Autoignition Temp Text:NP

Lower Limits:NONE

Upper Limits:NONE

Extinguishing Media:FOAM, DRY CHEMICAL, CARBON DIOXIDE, WATER SPRAY AS SUITABLE FOR SURROUNDING MATLS.

Fire Fighting Procedures:USE PROTECTIVE GEAR WITH SELF-CONTAINED BREATHING APPARATUS.

Unusual Fire/Explosion Hazard:HIGH DUST CONCEN FROM DRY FABRICATION MAY BE EXPLO IF MIXED W/AIR & IN PRESENCEN OF IGNITION SOURCE.

===== Accidental Release Measures =====

Spill Release Procedures:N

ONE-SOLID NON-HAZARDOUS MATERIAL.

===== Handling and Storage =====

Handling and Storage Precautions:AVOID DUST IN EYE/BLOWING DUST W/COMPRESSED AIR/PORL/REP BREATH OF DUST.AVOID OPEN FLAME/CONTACT W/OXIDIZ AGENTS.USE PROPER PERSONAL PROTECTION.

Other Precautions:NO SPECIAL HNDLG REQMTS.WHERE DUST IS STORED FOR DISPO,KEEP IN COOL AREA AWAY FROM HEAT/IGN SOURCES/OXIDIZING AGENTS.MAINTENANCE OF CONTAM EQPMT:KEEP OPN IGN SOURCES OUT OF AREAS W

HERE DUST GENERATED. ELECT GROUND/BOND ALL EQMPT USED (SUPPL)

===== Exposure Controls/Personal Protection =====

Respiratory Protection:WHERE SIGNIF EXPO TO NIUSANCE DUST POSSIBLE RESP SHOULD BE SELECTED BY/USED PER TRAIN HEALTH/SAF PROF IAW OSHA 29CFR1910.134/ANSI Z88.2-1992 REQMTS.IMPLEMENT TRAIN/WRITTEN RESP PROT PROGS/ETC.CONCEN B ELO TLV/PEL NIOSH APPROV DISPO (SUPPLE)

Ventilation:PROVIDE ADEQU GEN/LOC EXHAU VENTI-MAINTAIN AIRBORNE CONCEN BEL EXPO LIM

ITS/HEALTHFUL WORK CONDITIONS.ENCLS PROCESS(SUP)

Protective Gloves:NONE NEEDED.

Eye Protection:SAF GLASSES/GOGG IAW 29CFR1910.133.

Other Protective Equipment:NONE NEEDED.

Work Hygienic Practices:NONE SPECIFIED BY MANUFACTURER.

Supplemental Safety and Health

OTH PRECAUT:IN/AROUND PROCESSES INVOLVE DUST GENERATION(AVOIDS STATIC SPARKS). RESP:DUST/MIST RESP FOR PERSONAL COMFT.>TLV/PEL/10X LIMITS SEE ANSI STD.WARN:IR-PURIF RESP DONT PROTECT IN OXY DEF ATM. VENTI:WHERE POSSIBLE-PREVENT/M

IN DUST DISP INTO WORKAREA.

===== Physical/Chemical Properties =====

HCC:N1

Boiling Pt:B.P. Text:NP

Melt/Freeze Pt:M.P/F.P Text:NP

Decomp Temp:Decomp Text:NP

Vapor Pres:NP

Vapor Density:NP

Spec Gravity:SOLID

pH:NA

Viscosity:NP

Evaporation Rate & Reference:NP

Solubility in Water:NONE.

Appearance and Odor:SOLID, GLASS FABRIC-BASED MATL.NO DISCERNIBLE
ODOR.MFG,NON-HAZ PRODUCT.

Percent Volatiles by Volume:NP

Corrosion Rate:NP

===== Stability and Rea
ctivity Data =====

Stability Indicator/Materials to Avoid:YES

OXIDIZERS, STRONG ACIDS & BASES.

Stability Condition to Avoid:AVOID HEATING ABOVE 450F.

Hazardous Decomposition Products:CO₂, CO, HCN, SIMILAR TO WOOD
PRODUCTS.

===== Disposal Considerations =====

Waste Disposal Methods:EPA:NA. NONE SPECIFIED BY MANUFACTURER.

HMIS:FOLLOW ALL APPLICABLE LOCAL, STATE AND FEDERAL
REGULATIONS/LAWS.

Disclaimer (provided with this information by
the compiling agencies):

This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.