View NSN Online: https://aerobasegroup.com/nsn/8040-00-273-8703

## ITW DEVCON INDUSTRIAL CORP -- 5-MINUTE EPOXY RESIN -- 8040-00-273-8703

Product ID:5-MINUTE EPOXY RESIN

MSDS Date:02/19/1996

FSC:8040

NIIN:00-273-8703

Kit Part:Y

MSDS Number: CGNDL === Responsible Party ===

Company Name: ITW DEVCON INDUSTRIAL CORP

Address:30 ENDICOTT ST

City:DANVERS

State:MA

ZIP:01923-3753

Country:US

Info Phone Num:508-777-1100

**Emergency Phone Num** 

:800-424-9300 CAGE:JO304

=== Contractor Identification === Company Name: DEVCON CORP

Address:30 ENDICOTT ST

Box:City:DANVERS

State:MA

ZIP:01923-3753

Country:US

Phone:1-508-777-1100

CAGE:16059

Company Name: ITW DEVCON INDUSTRIAL CORP

Address:30 ENDICOTT ST

Box:City:DANVERS

State:MA ZIP:01923 Country:US

Phone:508-777-1100

CAGE:JO304

======= Composition/Information on Ingredients ========

Ingred Name: BISPHENOL A DIGLYCIDYL ETHER RESIN

Fraction by Wt: >60.0%

Other REC Limits: NONE RECOMM

ENDED
======================================
LD50 LC50 Mixture:LD50 RAT 11,400 MG/KG, ORAL MOUSE ** Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:EYE: IRRITATION, THERMAL BURNS. SKIN: IRRITATION, THERMAL BURNS, SENSITIZATION (RASHES, HIVES). INGEST: GASTRIC DISTRESS. CHRONIC: SENSITIZATION W/ITCHING, SWELLING OR RASHES. Medical Cond Aggravated by Exposure:P RE-EXISTING EYE AND SKIN DISORDERS. DEVELOPMENT OF PRE-EXISTING SKIN & LUNG ALLERGIES MAY INCREASE.
======================================
First Aid:EYE: FLUSH W/CLEAN WATER FOR 15 MINUTES, LIFT LIDS. SKIN: REMOVE CONTAM CLOTHES AND EXCESS CONTAMINATION. FLUSH SKIN W/WATER. WASH THOROUGHLY W/SOAP & WARM WATER. INHAL: GET FRESH AIR. OXYGEN IF NEEDE D. INGEST: DONT INDUCE VOMIT. DRINK 2 GLASSES OF WATER. IN ALL CASES, GET MED AID.
======== ======== Fire Fighting Measures ====================================
Flash Point Method:PMCC Flash Point:>400F,>204C Lower Limits:NE Upper Limits:NE Extinguishing Media:CARBON DIOXIDE, DRY CHEMICAL, FOAM. Fire Fighting Procedures:IN CONFINED SPACES, USE FULL BUNKER GEAR. FIRE FIGHTERS SHOULD USE SCBA AND PROTECTIVE CLOTHING. COOL CONTAINERS W/WATER.
Unusual Fire/Explosion Hazard:HEATING >300F IN THE PRESENCE OF AIR MAY CAUSE SLOW OXIDATIVE DECOMP. >500F MAY CAUSE POLYMERIZATION.
======= Accidental Release Measures ===============
Spill Release Procedures:ELIMINATE IGNITS. VENT AREA. DIKE, CONTAIN & ABSORB W/SUITABLE MATERIAL. LGSP: PUMP TO STORAGE/SALVAGE VESSELS. SOAK UP RESIDUE W/ABSORBENT. FLUSH AREA W/WATER. PREVENT FROM ENTERING DRAINAGE/SEWER SY STEM/WATERWAYS/SURFACE WATERS.
======================================
Handling and Storage Processions: STORE IN A COOL DRY AREA AWAY FROM

Handling and Storage Precautions:STORE IN A COOL DRY AREA AWAY FROM HIGH TEMPS AND FLAMES.

Other Pre

