View NSN Online: https://aerobasegroup.de/nsn/6505-01-360-0908 NATIONAL WELDERS SUPPLY CO INC -- NITROGEN -- 6505-01-360-0908 Product ID:NITROGEN MSDS Date:01/01/1991 FSC:6505 NIIN:01-360-0908 Status Code:A MSDS Number: CLJBH === Responsible Party === Company Name: NATIONAL WELDERS SUPPLY CO INC Address:810 GESCO ST Box:31007 City:CHARLOTTE State:NC ZIP:28231 Country:US Info Phone Num:704-333-5475 Emergency Phone Num:(800)424 -9300 Preparer's Name: HENRY SIMMONS Chemtrec Ind/Phone:(800)424-9300 CAGE:18264 === Contractor Identification === Company Name: NATIONAL WELDERS SUPPLY CO INC Address:810 GESCO ST Box:31007 City:CHARLOTTE State:NC ZIP:28231 Country:US Phone:704-333-5475 CAGE:18264 ======= Composition/Information on Ingredients ========

Ingred Name: NITROGEN CAS:7727-37-9

RTECS #:QW9700000

============= Hazards Identification ========================

Effects of Overexposure: EFFECTS OF EXPOSU

RE TO HIGH CONCENTRATION SO AS TO DISPLACE THE OXYGEN THE OXYGEN IN AIR NECESSARY FOR LIFE MAY INCLUDE ANY, ALL, OR NONE OF THE FOLLOWING: LOSS OF BALANCE OR DIZZINESS; TIGHTNESS IN THE FRONTAL ARE OF THE FOREHEAD; TINGLING OF THE TONGUE, FINGERTIPS OR TOES; WEAKENED SPEECH LEADING TO THE TO THE **ABILITY TO** PERFORM MOVEMENTS: REDUCE CONSCIOUSNESS OF THE SURROUNDING: LOSS OF TACTILE SENSATIONS: HEIGHTENED MENTAL ACTIVITY. IT SHOULD BE RECOGNIZED THAT IT IS POSSIBLE THAT NO NE OF THE ABOVE SYMPTOMS MAY OCCUR IN NITROGEN ASPHYXIA SO THAT THERE ARE NO DEFINITE WARNING SYMPTOMS. First Aid:PROMPT MEDICAL ATTENTION IS MANDATORY IN ALL CASES OF OVEREXPOSURE TO NITROGEN. RESCUE MEDICAL ATTENTION IS MANDATORY IN ALL CASES OF OVEREXPOSURE TO NITROGEN. RESCUE PERSONNEL SHOULD BE EQUIPPED WITH SELF-CONTAINED BREATHING APPARATUS. INHALATION: CONSCIOUS PERSON SHOULD BE ASSISTED TO AN UNCONTAM INATED AREA AND INHALE FRESH AIR. QUICK REMOVAL FROM THE CONTAMINATED IS MOST IMPORTANT. UNCONSCIOUS PERSONS SHOULD BE MOVED TO AN UNCONTAMINATED AREA, GIVEN MOUTH-TO-MOUTH RESUSCITATION AND SUPPLEMENTAL OXYGEN. Extinguishing Media: NONFLAMMABLE, INERT GAS ======== Accidental Release Measures ============= Spill Release Procedures: EVACUATE ALL PERSONAL FROM AFFECTED AREA. USE

APPROPRIATE PROTECTI

VE EQUIPMENT. IF
LEAK IS IN CONTAINER OR CONTAINER VALVE, CONTACT YOUR CLOSET SUPPLIER
LOCATION OR
CALL THE EMERGENCY TELEPHONE NUMBER LISTED HEREIN.

========== Handling and Storage ===============

Handling and Storage Precautions: USE ONLY IN WELL VENTILATED AREAS. VALVE PROTECTION CAPS MUST REMAIN IN PLACE

UNLESS CONTAINER IS SECURED WITH VALVE OUTLET PIPES TO USE POINT. DO NOT DRAG, SLIDE

OR ROLL CYLINDERS. USE A SUITABLE HAN D TRUCKER BY ANY MEANS TO INCR

EASE THE

DISCHARGE RATE OF PRODUCT FROM CYLINDER.

Other Precautions:COMPRESSED GAS CYLINDERS SHOULD NOT BE REFILLED EXCEPT BY QUALIFIED PRODUCERS OF

COMPRESSED GASES. SHIPMENT OF A COMPRESSED GAS HAS NOT BEEN FILLED BY THE OWNER OR

WITH HIS (WRITTEN) CONSENT IS A VIOL ATION OF FEDERAL LAW (49CFR).

====== Exposure Controls/Personal Protection ========

Respiratory Protection: POSITIVE PRESSURE AIR LINE WITH MASK OR SELF-CONTAINED BREATHING APPARATUS SHOULD BE AVAILABLE FOR

EMERGENCY USE.

Ventilation: TO PREVENT ACCUMULATION OF HIGH CONCENTRATIONS SO AS TO REDUCE THE OXYGEN LEVEL IN THE AIR TO LESS THAN 18 MOLAR PERCENT.

Protective Gloves: ANY MATERIAL

Eye Protection: SAFETY GOGGLES OR GOGGLES.

Other Protective Equipment: SAFETY SHOES.

Supplemental Safety and Health

======== Physical/Chemical Properties ==========

Boiling Pt:=-195.8C, -320.5F Melt/Freeze Pt:=-209.9C, -345.9F

Vapor Pres:21.1C ABOVE CRITICAL TEMP

Spec Gravity:.97

Solubili