NSN 1615-01-599-0390

Tail Rotor Drive Shaft Assembly - Page 1 of 1



View Online at https://aerobasegroup.de	le/nsn/1615-01-599-0390
---	-------------------------

view Chiline at https://acrobasegroup.ac/hsh/1010 01 000 0

Shelf Life:

N/a

Unit Of Measure:

1 ea

Demilitarization:

Yes - demil/mli

Fiig:

A23900

Hazmat:

No

Repairability:

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.