NSN 1620-01-125-6999

Repairability:

Tail Bumper Yoke Assembly - Page 1 of 1



View Online at https://aerobasegroup.de/nsn/1620-01-125-6999	
Shelf Life:	
N/a	
ਪਕ Unit Of Measure:	
1 ea	
Demilitarization:	
Yes - demil/mli	
Hazmat:	
No	
NO NO	

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.