NSN 1680-01-540-7176

Repairability:

Aircraft Interior Lining Panel - Page 1 of 1



iew Online at https://aerobasegroup.de/nsn/1680-01-540-7176	
helf Life:	
/a	
nit Of Measure:	
ea	
emilitarization:	
es - demil/mli	
iig:	
11700	
azmat:	
0	

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.