## NSN 2835-01-442-9021

Repairability:

Nonaircraft Gas Turbine Engine Compressor Rotor - Page 1 of 1



When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.