NSN 2840-00-327-7579

Repairability:

Aircraft Gas Turbine Engine Combustion Chamber Case - Page 1 of 1



View Online at https://aerobasegroup.de/nsn/2840-00-327-7579	
: :	
:	
Shelf Life:	
N/a	
Unit Of Measure:	
1 ea	
Demilitarization:	
Yes - demil/mli	
Fiig:	
A10700	
Hazmat:	
No	

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.