NSN 2840-01-143-9806

Repairability:

Aircraft Gas Turbine Engine Combustion Chamber - Page 1 of 1



View Online at https://aerobasegroup.de/nsn/2840-01-143-9806	
• • • • • • • • • • • • • • • • • • •	
:	
Shelf Life:	
N/a	
Unit Of Measure:	
1 ea	
Demilitarization:	
Yes - demil/mli	
Filig:	
A530f0	
Hazmat:	
No	

When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.