## NSN 4820-01-111-8533

No

Repairability:

Ball And Seat Assembly - Page 1 of 1



When repair is beyond lower level maintenance capability, evacuate the item to depot. disposal is not authorized below wholesale level.